APPENDIX B CRS FORM FOR WARD HOUSE (CRS #S-3212)

CULTURAL RESOURCE SURVEY STRUCTURAL DATA FORM

DELAWARE BUREAU OF ARCHAEOLOGY AND HISTORIC PRESERVATION HALL OF RECORDS DOVER, DELAWARE 19901 (302) 736 - 5685




FOR OFFICE USE ONLY

CRS # S3212
Quad Georgetown
SPO map # 14-15-11
Hundred Georgetown
DOCUMENT 20-06/78/08/14

(302) 736 - 5685

1. ADDRESS OF STRUCTURE: Road 244, 1/10 mile E of Road 246

- 2. DESCRIBE THE STRUCTURE AS COMPLETELY AS POSSIBLE:
 - a) Overall shape T-plan stories $1 \ 1/2$ bays 3 wings 1 at rear
 - b) Structural system
 - c) Foundation brick materials basement
 - d) Exterior walls materials weatherboard color(s) gray



- e) Roof
 shape; materials side gable; asphalt shingles
 cornice
 dormers
 chimney location(s) at each gable end, within walls
- f) Windows
 spacing regular
 type 2/2 double hung first, 2-light fixed in attic
 trim plank, some with molded drip shelves
 shutters
- g) Door
 spacing left of center
 type three horizontal panels below plate glass
 trim plank
- h) Porches
 location(s) along side of rear wing
 materials wood
 supports
 trim
- i) Interior details (if accessible) large brick fireplace at SW wall, with enclosed stair with winders in corner; simple wooden mantels in NE rooms on both floors.

USE BLACK INK ONLY

3.	CONDITION:	good <u>x</u>	deteriorated		
	remarks:	house has been "preser	ved" through inclusion within a	equipment shed	
4.			b) moved		
	С) if moved, when and fr	rom where <u> </u>		
			ns and dates (if known) <u>rear e</u>		
		metal garage and equ	ipment shed added 1987		
5.	DATE OF INITIA	DATE OF INITIAL CONSTRUCTION: ca. 1880			
6.	ARCHITECT/BUILDER: unknown				
7.	RELATED OUTBUILDINGS:				
	a) barn	b) carriage house	c) garage d) privy	/	
	e) shed	f) greenhouse	g) shop h) gardens		
	i) iceho	use j) springhouse	e k) otherX		
	describe	: post 1976 mobile home	e, garage, shed and dog house		
			<u></u>		
8.		SS THE ORIGINAL AND SUB WITH HISTORIC EVENTS OR	SEQUENT USES OF THE STRUCTURE. PERSONS:	NOTE ANY	
			Ward, subsequently passed to	his youngest	
	son, Frank Wa	ru, 1n 1912.			
		·			
9. Primary References: (include location of reference). Phase I Cultural Resource Survey of Wetland Mitigation Site No. 5, US Route 113,					
F	Milford-Ge	orgetown. Prepared by I	Louis Berger & Associates, Inc.	for Delaware	
	pepartment	of Transportation, 1992	۷.		
1	0. Surveyor:	M. Bowers	Date of Form:	11/92	
USE BLACK INK ONLY					

CULTURAL RESOURCE SURVEY LOCUS IDENTIFICATION FORM

DELAWARE BUREAU OF ARCHAEOLOGY AND HISTORIC PRESERVATION HALL OF RECORDS DOVER, DELAWARE 19901 (302) 736 - 5685



FORM CRS-3

FOR OFFICE USE ONLY

CRS # S3212

Quad Georgetown


SPO map # 14-15-11

Hundred Georgetown

DOCUMENT 20-06/78/04/7

1.	NAME OF LOCUS: Glen Eskridge Property (William H. Ward House)			
2.	STREET LOCATION: SR 244, 1/10 mi. e. of Road 246			
3.	OWNER'S NAME: Glen Eskridge TEL. #			
	ADDRESS: Route 4, Box 65A, Georgetown, DE 19947			
4.	TYPE OF LOCUS: a) structure X b) district c) archaeological site			
	d) other			
5.	SURROUNDINGS OF LOCUS: (check more than one if necessary)			
	a) fallow field b) cultivated field X c) woodland			
	d) scattered buildings e) densely built up f) other			
6.	THREATS TO LOCUS: (check more than one if necessary)			
	a) none known b) zoning c) roads d) developers			
	e) deterioration f) other <u>acquisition</u> for borrow and wetland development			
7.	REPRESENTATION ON OTHER SURVEYS:			
	TITLE: Sussex Preservation Office Inventory 1983 #			
	TITLE:#			
	TITLE:##			
8.	YOUR NAME: M.Bowers TEL. # 201-678-1960			
	YOUR ADDRESS: 100 Halsted Street, East Orange, New Jersey 07019			
	ORGANIZATION (if any)Louis Berger & Associates, Inc. DATE: 11/92			

USE BLACK INK ONLY



9. COMMENTS:

Consider the following:

- a) relationship to setting
- b) associated traditions or stories
- c) noteworthy features
- d) comparison with others in area

Ca. 1880 frame hall-parlor house (presently hidden beneath a large pole and metal equipment shed) is largely intact example of its kind. Includes large stone and brick fireplace, and enclosed corner stair with winders. Other buildings on the property are very recent, including the occupied mobile home.

- 10. Comprehensive Planning:
 - a. Time Period(s)
 - b. Cultural Concept
- 11. Evaluation:
 - a. Settlement & Development
 - b. Cultural Historic & Ethnic Issues
 - c. Built Environment
 - d. Material Culture
 - e. not eligible

Survey: Name/Title BAHP: Name/Title __ Date_ Date

USE BLACK INK ONLY